



SmartFuse



Electrofusion control unit

Instruction Manual

1. Variants

NOTE



Device variants

This instruction manual describes the following device variants:

SmartFuse

Table of contents

1.	Variants	2
2.	Information about this manual	7
2.1.	Applicable Documents	7
2.2.	Warnings	
2.2.1.	Description of the structure of the warnings	
2.2.2.	List of warnings	
2.3.	Symbolism	
2.3.1. 2.3.2.	General symbols and signs	9 a
2.3.3.	Requirement symbols	
2.3.4.	Prohibition symbols	
3.	Warranty and liability	10
4.	Identification	11
4.1.	Product labeling	
4.2.	Information about the manufacturer	
4.3.	Type plate	11
5.	Product description	12
5.1.	Purpose and intended use	12
5.2.	Improper use	
5.3.	Modifications and alterations	
5.4.	Ambient conditions	
5.4.1. 5.4.2.	Environmental conditions	
5.4.∠. 5.5 .	Weight	
5.6.	Overview and component description	
5.7.	Safety features	
5.7. 5.7.1.	General	
5.7.2.	List of safety features on the product	
6.	Safety	13
6.1.	General safety guidelines for power tools	14
6.1.1.	Duty of care of the operator	
6.1.2. 6.1.3.	Duty of care of the user	
6.1.4.	Safety in the work area	
6.1.5.	Personal safety	
6.1.6.	Power tool usage and care	
6.1.7.	Service	
6.2.	Specific safety guidelines for the electrofusion control unit	
6.2.1. 6.2.2.	Electrical safety Personal safety.	
6.3.	Peronal protective equipment	
6.4.	Qualification of personnel	
6.5.	Deadlines for recurring checks	
	•	

6.6. 6.6.1. 6.6.2.	Dangers during individual work phases Dangers during transport and assembly Dangers during operation	.20
6.6.3.	Dangers during removal	.20
6.7.	Device specific dangers	
6.8.	Residual risk	
7.	Scope of delivery	21
8.	Technical data	22
8.1.	Data recording	.23
9.	Input of welding parameters	24
9.1.	SmartFuse-System*	.24
10.	Range of fitting dimensions	25
11.	Bluetooth functionality	25
12.	Spare parts and accessories	26
13.	Transport, Installation and removal, storing	26
13.1.	Transport damage	.26
13.2.	Packaging	
13.3.	Assembly and installation	
13.4.	Storage	.27
14.	Connection to the power supply	27
14.1.	General	.27
14.2.	Extension lines	
	General For Australia	
14.2.2.	Generator compatibility	
	Required generator rated output power	.29
15.	Preparation of a welding procedure	30
15.1.	General checks and measures before usage	.30
15.2.	Switching the electrofusion control unit on	
	Other display messages	
15.3.	Pairing via Bluetooth Option "BT on" active, "BT only" inactive	.32
	Option "BT on" active, "BT only" inactive	
	Pairing via Bluetooth is finished	
15.4.	Main display	
15.5.	Displaying device data	
16.	Performing the welding process	35
16.1.	Important information	
16.2.	Connect Fitting	
16.3.	Welding with SmartFuse	
	Reminder to clamp the pipes	

16.3.3.	After the end of the welding procedure	.37
17.	Function menu	. 38
17.1.	Using the letter field to enter data	.39
17.2.	Job no	.40
17.2.1.	Entering a job number (commission number)	.40
17.2.2.	Creating a job number (commission number)	.40
17.3.	USB	.41
17.3.1.	Transfer reports to a USB stick	.42
17.4.	Erase reports	
17.5.	Contrast (Display)	.45
17.6.	Volume	.46
18.	System config.	. 47
18.1.	Menu navigation	.47
18.2.	Language	.48
18.3.	Inv. number	.48
18.4.	Set clock	
18.5.	Update	
18.6.	Memory control	
18.7.	Daylight time	
18.8.	Weldername	
18.9.	Job no.	
18.10.	South	
18.11.	Cont. numbers	.50
18.12.		
18.13.	Code Sys	.51
18.14.	Code Del	.51
18.15.	Secure data	.51
18.16.	BT on	.52
18.17.	BT only	.52
19.	Maintenance and troubleshooting	. 53
19.1.	Qualification of personnel	.53
19.2.	Maintenance by laymen	.53
19.3.	Maintenance by specialists	.53
19.4.	Maintenance cycles for safe operation	.54
19.5.	Measures after maintenance or servicing	
19.6.	Cleaning	
19.7.	Replacement of the welding terminals	
20.	Error messages E1-E30	. 55
20.1.	Error messages E250-E285	
20.2.	Bluetooth error messages	
21.	Maintenance and service by the customer service	. 56
21.1.	Wearing parts	

21.2.	Addresses of service stations	57
21.3.	Repackaging before transport	57
22.	Decommissioning, Disassemble, Disposal	57
22.1.	Environment-friendly disposal	57
22.1.1.	General	57
22.1.2.	Batteries and accumulators	58
23.	Declaration of conformity C€	58
24.	Administrator code	58
25.	PLASSON subsidiaries worldwide	59

2. Information about this manual

This document has been prepared by PF Schweißtechnologie GmbH. All rights to this document, in particular the right of reproduction, placing on the market and translation into other languages, remain exclusively with PF Schweißtechnologie GmbH.

No part of the document may be altered, copied, electronically processed or distributed without the prior written consent of PF Schweißtechnologie GmbH.

Read this instruction manual completely. The handling and use of the product described below are not always self-explanatory. Therefore the knowledge of the technical documentation is obligatory.

Only in this way can you use the product properly, correctly, safely and effectively.

If parts of the technical documentation are damaged, illegible or lost contact your dealer or the manufacturer to obtain the documents again.



Residual risk

This document informs you about remaining residual risks against which construction and protective measures are not or only partially effective.



Errata and technical modifications reserved!

All notes and technical specification in this instructions manual were prepared with all necessary care. The manufacturer reserves all rights for technical modifications of the product or its components without prior notice to customers. Technical modifications cannot always be directly transferred to the documentation. If you are in doubt about the topicality of the documentation please contact your distributor or the manufacturer.

2.1. Applicable Documents

Document

This product does not have additional documentation.





Read the entire documentation!

Using the product or its components without completely reading and understanding the entire documentation shall be considered as improper use and is strictly forbidden.

2.2. Warnings

When using the product, it is always necessary to carry out activities in which danger may occur. In this document, dangerous situations are preceded by warnings, which must be observed under all circumstances.

2.2.1. Description of the structure of the warnings

The warnings are provided with a signal word and one or more symbols. The signal word with the pictogram describes the severity of the danger. Below is an example for clarification.

A CAUTION (A)



Hazard description (B)

Further explanation on the nature and cause of the danger (C)

> Measures to prevent or avoid the danger (D)

Symbol	Information	Content	Example
0	Signal word	Classification of the danger by symbol and signal word	Caution
В	Danger description	What is the danger and when does it occur?	Danger due to hot surface
С	Possible consequences if the danger occurs	What will or can happen if you do not pay attention to the warning?	The hot surface can cause burns.
D	Measures to avoid the danger		Keep your distance and wear fire resistant gloves.

2.2.2. List of warnings



General remark

This is a remark of a general nature. These advices describe recommended courses of action to enable the user to perform steps quicker and safer. This warning symbol can also indicate important or obligatory general conditions.

NOTE



Potentially harmful situation

This signal word indicates a possible dangerous situation for the product, its components, accessories and / or the environment.

A CAUTION



Potentially dangerous situation

This signal word indicates a danger with a low degree of risk. Failure to do so could result in minor or moderate injury.

A WARNING



Dangerous situation

This signal word indicates a danger with a medium degree of risk. Failure to do so may result in serious injury or death.



Immediate danger

This signal word indicates a danger with a high or very high degree of risk. Failure to do so will result in serious injury or death.

2.3. Symbolism

In this document, various symbols are used as aids. The meaning of each is explained below.

2.3.1. General symbols and signs

Symbol/sign

Explanation



Important information

2.3.2. Warning symbols

Symbol

Explanation



General warning symbol



Warning: Electricity



Warning: Hot surface

2.3.3. Requirement symbols

Symbol/sign Explanation

General requirement

Information about / in the documentation
This symbol indicates that special attention must be paid to the technical

documentation.

Wear safety shoes!

Ground before use!

Pull out the mains plug!

2.3.4. Prohibition symbols

Symbol/sign Explanation

General prohibition

No reaching in!

3. Warranty and liability

Warranty and liability claims for personal injury and property damage are excluded if they are attributable to one or more of the following causes:

- > Improper use of the product and its components outside its scope of application.
- Improper assembly, commissioning, operation, maintenance and improper transport of the product including its components.
- Operation of the product including its components with defective or improperly installed safety devices.
- Failure to follow the instructions in the instruction manual.
- > Unauthorized structural changes on the product or its components.
- > Poor monitoring of parts that are subject to wear.
- Repairs carried out improperly.
- Disasters due to foreign bodies and force majeure.

4. Identification

4.1. Product labeling

Product description: Electrofusion control unit

Product type: Electrofusion control unit for welding thermoplastic pipelines using fittings with an input voltage below 48 V.

4.2. Information about the manufacturer

 PF-Schweißtechnologie GmbH
 Tel.:
 +49-6631-9652-0

 Karl-Bröger-Str.10
 Fax.:
 +49-6631-9652-52

 DE-36304 Alsfeld
 E-Mail:
 info@pfs-gmbh.com

 Germany
 Web:
 www.pfs-gmbh.com

4.3. Type plate

The type plate is a unique identifier of the product and is structured as follows:

Netz/Supply: 230V~ / 50/60Hz

Leistung/Power: 2800VA/80%ED

Schutzart/Protection: IP54

Made in Germany WEEE: DE27521436

PF-Schweißtechnologie GmbH

Karl-Bröger-Str.10 Tel: +49-6631-9652-0
DE-36304 Alsfeld Fax +49-6631-9652-52

(5) Heizwendelschweißgerät / Electro Fusion Control Box

Typ: Polymatic Plus USB (BT)

7) S/N: 20810093

8 Art.: 3 0308 303



CF

ၜၟ႞

DE,GB,FR,ES,PT,IT,RO

No. Description

- 1 Input voltage / input frequency
- 2 Power at 80% ON time
- 3 IP protection class
- 4 Manufacturer
- 5 Type description of the device
- 6 Device designation
- 7 Serial number
- 8 Product code
- 9 Available display languages

5. Product description



Note

When the term "Electrofusion control unit" is used, this includes all variants of the tool. Otherwise, details of each specific feature will be mentioned seperately.

5.1. Purpose and intended use

The electrofusion control units of type SmartFuse are solely meant for the welding of thermoplastic pipes (e.g. made of PE-HD, PE80, PE100 or PP) when used with electrofusion fittings that have an input voltage of less than 48 V. These devices are conforming to the standards DVS 2208-1 and ISO 12176-2, of which the applicable standards for the electrofusion fittings to be used are derived from.

5.2. Improper use



Disclaimer!

The product may not be used for any purposes other than those mentioned. The basic conditions mentioned must be adhered to. The use of the product as a whole or parts thereof for purposes other than those mentioned above shall be considered as improper use.

The operator or user is liable for improper use!

5.3. Modifications and alterations

Modifying the product without prior consulting of the manufacturer is forbidden and shall be considered as improper use.



Constructional modifications are subject to prior approval!

No modifications, additions or conversions of the product or its components may be made without the manufacturer's approval.

In the case of infringements, the warranty and liability claims shall be void.

5.4. Ambient conditions

5.4.1. Environmental conditions

None


5.4.2. Weight


No special arrangements required.

5.5. Assembly and mounting

No special arrangements required.

5.6. Overview and component description





- 1 Cable holder and carrying handle
- 2 Signal horn
- 3 Welding cable
- 4 Carrying handle
- 5 USB interface
- 6 ON-OFF-switch
- 7 Temperature sensor
- 8 Mains supply cable

- 9 Display
- 10 Green start button
- 11 Red stop button
- 12 Arrow buttons ▲ ▼ ◀▶
- 13 Enter button

5.7. Safety features

5.7.1. General

Safety features on the product or its components serve to protect operators. The product may only be used if all safety-related equipment is present and fully functional.

5.7.2. List of safety features on the product

None

6. Safety

Our electrofusion control units are built according to the latest state of the art and the recognized safety regulations and directions. Nevertheless, dangers to the user or other nearby persons, as well as damage to property values, may arise if the use is improper, easy or incorrect.

The electrofusion control unit and its components may only be used when the following preconditions are met:

- > The use may only be carried out within the scope of the intended use.
- > The electrofusion control unit and its components must be generally and mechanically in perfect condition.

6.1. General safety guidelines for power tools

The basic condition for safely handling and a hassle-free operation of the product is the knowledge about the fundamental safety guidelines and safety regulations. This instruction manual contains essential information on how to handle the product, including its components and acessories, safely. The safety guidelines have to be acknowledged and observed by everyone working with the product. These instructions shall be read and implemented in accordance with the relevant standards, workplace health and safety legislation, installation instructions, Codes of Practice and technical connection guideline in force in your country.

- > Read and make sure you understand all safety guidelines and instructions. Failure to follow the safety guidelines and instructions can lead to electric shock, fire and/or serious injury.
- > Keep these safety guidelines and instructions for future use.
- > The term "power tool" used in the safety guidelines relates to mains-operated power tools (with cord) as well as battery-operated power tools (without cord).

NOTE



Read the provided documentation!

Read the provided documentation thoroughly to prevent applications errors and to work safer and according to the scope of application with the respective product. Reading the documentation thoroughly and completely helps preventing accidents due to improper use and eases the work with the product.

All users of the product must thoroughly read and understand the provided documentation prior to use.






Danger due to non-compliance with accident prevention regulations!

In order to be able to use the product safely, the knowledge of the applicable accident prevention regulations in your country is absolutely necessary. Working with the product without the knowledge of the valid accident prevention regulations carries a great risk for irreversible injuries and property damage.

- > Germany: Familiarize yourself with the general accident prevention regulations (UVV).
- International: International: Familiarize yourself with the standards and regulations for accident prevention in your country. Take note of these and act accordingly.

6.1.1. Duty of care of the operator





Minimizing risks

Above all, the safety at the place of installation of the product can only be achieved if all necessary risk-minimizing measures are taken and avoidable risks are ruled out from the outset. This is the duty of care of the operator. All users of the product must thoroughly read and understand the provided documentation prior to use.

The operator is obliged to allow the usage of the product only to people that:

- > are familiar with the basic regulations on work safety and accident prevention and are thoroughly instructed in the proper handling of the product, its components and accessories.
- have read and understood the complete documentation of the product, its components and accessories
- > are sufficiently qualified and authorized to use the product as intended.
- are fully trained and familiarized with the process of welding PE pipelines.

Furthermore, the operator must ensure that:

- responsibilities of the staff / user shall be clearly defined with regard to transport, installation, dismantling, commissioning, setting up and adjustment, operation, maintenance and inspection, repair and disassembly.
- > the product and its components are used only in accordance with the intended use.
- the product, its components and accessories is used only together with accessories and retrofit parts provided by the manufacturer.
- > the product and its components must be in perfect and functional condition.
- > the parts of the personal protective equipment necessary for carrying out the work are available and used for the personnel employed.
- the documentation associated with the product and its components is always fully and legibly available on the job site.
- at each change of ownership, or when loaned to other persons, all documentation must be included and its importance pointed out.
- > the general and local regulations for accident prevention and environmental protection are provided.
- all safety and danger warnings on the product, its components and accessories are kept in readable condition and renewed if damaged.

Technical condition of the product:

Subsequent requirements are based on the technical condition of the product. Compliance with these requirements must be ensured by the operator.

- > The product may only be used as intended.
- The product must be checked for perfect technical condition before each use.
- No unauthorized or arbitrary modifications or manipulations of the product, its components or accessories may be made.
- The full technical documentation must always be kept completely and legibly at the place of use of the product for inspection.

6.1.2. Duty of care of the user

All persons who are instructed to work with the product have the obligation to:

- familiarize themselves with the basic regulations on work safety and accident prevention before starting to work.
- > thoroughly read the entire documentation.
- inform oneself about the functioning of the product, its components and accessories.

6.1.3. Safety in the work area

- Keep your work area clean and well lit. Working in cluttered or dark areas can easily lead to accidents. Prevent the electrofusion control unit from unintentional movement or dropping.
- Do not work with the electrofusion control unit in potentially explosive areas in which flammable liquids, gases or dust are present. Power tools can produce sparks, which can ignite dust or fumes.
- Keep children and bystanders at distance while operating a power tool. Distractions can cause you to lose control over the electrofusion control unit. Do not allow other people touch the electrofusion control unit or cables and keep them away from your working place. Run cables neatly to avoid trip accidents. It is preferable to elevate cables on cable stands.

6.1.4. Electrical safety

- The plug of the electrofusion control unit must fit in the outlet. Never modify the plug in any way. Do not use any adapters in combination with earthed/grounded electrofusion control units. Unmodified plugs and matching outlets will reduce the risk of electric shock.
- Avoid physical contact with earthed/grounded surfaces or objects such as pipes, radiators, stoves and refrigerators whilst operating power tools. There is an increased risk of electric shock if your body is earthed/grounded.
- Keep electrofusion control units clear of rain and wetness. Water entering a electrofusion control unit will increase the risk of an electric shock
- Do not misuse the cord of the electrofusion control unit for carrying it, hanging it up or pulling the plug out of the socket. Keep the cord away from heat, oil and sharp edges. Damaged or bent cords increase the risk of an electric shock.
- > Do not carry the electrofusion control unit with the finger on the power switch. Pull out the plug when you do not use the electrofusion control unit or when changing the adapters and attachments.
- When operating an electrofusion control unit outdoors, use an extension cord suitable and approved for outdoor use. Usage of a cord suitable for outdoor use reduces the risk of an electric shock.
- Always use a residual current-operated protective device (RCD). Using an RCD reduces the risk of an electric shock.

6.1.5. Personal safety

- Stay alert! Watch what you are doing and use common sense when operating an electrofusion control unit. Do not use an electrofusion control unit while being tired or under the influence of drugs, alcohol or medication. One moment of inattention while operating an electrofusion control unit can cause serious personal injury.
- Use personal protective equipment and always wear eye protection. The use of protective equipment such as a dust mask, non-skid safety shoes, a hard hat or hearing protection, depending on the electric tool and its use will reduce personal injuries.
- Prevent unintentional starting of the device. Make sure that the electrofusion control unit is switched off before connecting it to the mains and/or battery or before picking it up/carrying it. Carrying the electrofusion control unit with a finger on the switch or energising electrofusion control units that are switched on can cause injuries and accidents.

6.1.6. Power tool usage and care

- Do not overload the electrofusion control unit! Use the appropriate electrofusion control unit for your application. When using an appropriate power tool you can work better and more safely in its range of capacity.
- > Do not use an electrofusion control unit if the switch is broken. An electrofusion control unit, which cannot be turned on or off, is dangerous and must be repaired.
- Keep and store electrofusion control units away from children. Do not let people, who are not familiar with the electrofusion control unit or have not read and understood the instruction manuals, use it. Electrofusion control units are dangerous if being used by inexperienced users.
- Maintain electrofusion control units with care. Check for misalignment or binding of moving parts, breakage of parts and any other condition that may affect the electrofusion control unit's operation. If damaged, have the electrofusion control unit repaired before use. Many accidents are caused by poorly maintained electrofusion control units.
- > Keep your electrofusion control units clean. Follow the servicing instructions and the instructions for changing the tools. Keep oil and grease away from the handles.
- > Use the electrofusion control unit, accessories etc. in accordance with these instructions. Take the working conditions and the work to be performed into account. The use of the electrofusion control unit for applications differing from the application scope could result in a hazardous situation.

6.1.7. Service

Have your electrofusion control unit repaired only by a qualified technician with genuine spare parts. This ensures that the safety of the electrofusion control unit is maintained.

6.2. Specific safety guidelines for the electrofusion control unit

6.2.1. Electrical safety

- The use of a residual current-operated protective device (RCD) is mandatory when working at outdoor construction sites. Note all directives and technical connection regulations in force in your country. It can be mandatory to always use a residual current-operated protective device (RCD).
- According to national and international guidelines, the use of > 230 V AC or higher (or > 110 V AC or higher) in trenches and confined spaces is only permitted if additional security measures are taken. Each electrical device operated in such an environment has to be powered by its own safety isolating transformer or its own insulation protective device.
- Only use accessories, particularly extension cords and generators, that are specified/recommended in this instruction manual. The use of any other accessories can damage the electrofusion control unit and increases your risk of injury.
- Before each use, the user must visually inspect that the electrofusion control unit, its cables and accessories as well as its electrical supply cord to ensure that all parts are free from damage.Damaged protection facilities and device parts must be repaired or replaced by an authorized service agent.
- In accordance with the workplace health and safety legislation in force in your country for connection and usage of electric devices you must ensure that the electrofusion control unit, any extension cords and RCDs are regularly inspected (tested and tagged) by a licensed electrician or other competent person.
- It is very important that there is a Protective Earthing (PE) conductor which is continuous (i.e. <0.5 Ohms) from the earth terminal of the generator to the earth terminal of the plug on the flexible supply cord of the electrofusion control unit. If the protective earthing conductor is interrupted or becomes higher in resistance, there is a risk of electric shock.</p>

6.2.2. Personal safety

- Pipes and other workpieces must be firmly clamped or fixed. Poorly clamped or fixed workpieces may hurt you or affect your safe foothold.
- > If the electrofusion control unit is used on a generator, the generator shall be grounded. Otherwise there is a risk of an electric shock.
- The electrofusion control unit shall only be used on a power circuit with a protective earthing conductor. Otherwise there is a risk of an electric shock.

6.3. Peronal protective equipment





Obligation to use the personal protective equipment!

During transport, assembly, assembly and disassembly of the product, the respective personnel must wear and use the appropriate PPE.

Which parts of the PPE must be used must be evaluated on an individual basis, determined by the operator and announced to the personnel.



The nature and extent of the PPE to be worn must be assessed and determined for the individual case.

The following PPE is recommended when working with this product:



Wear safety shoes!

Wearing safety shoes protects the feet from falling objects and reduces the risk of slipping.

6.4. Qualification of personnel

Only persons with sufficient knowledge in the field of welding PE pipelines may work with this product. This knowledge may have been gained through several years of professional experience, training, instruction or other training. Persons who do not have sufficient knowledge in this area must be supervised and instructed by a person with appropriate knowledge.



Danger due to insufficient personnel qualification

If insufficiently skilled operators work with the product or are in the work area, there is a risk of serious injury or property damage.

- Allow only qualified personnel to work with the product.
- Personnel in training may only work with the product under the supervision of an experienced person.

6.5. Deadlines for recurring checks

Action	Interval
Cleaning the product after completion of the work.	Each working day
Check the welding and mains cable for damage.	Each working day
Check the terminals for damage and sufficient contact force.	Each working day
Maintenance by the manufacturer or an authorized service station	Annual

6.6. Dangers during individual work phases

6.6.1. Dangers during transport and assembly

Transport

No special dangers.

Installation

No special dangers.

6.6.2. Dangers during operation

The operator must have been instructed by the operator in the handling of the product. Working with the product without instruction is prohibited. The proof obligation lies with the operator.

Use the product only in accordance with its intended use. Activities that impair safety are to be avoided.

$oldsymbol{\Lambda}$ warning



Injury due to improper / unintended operation

Incorrect or unintentional operation of the product can lead to injury and / or property damage.

- Before using the product, check that all components are free from damage.
- Never operate the product if it has any damage.

6.6.3. Dangers during removal

The disassembly of the components may only be carried out by trained personnel who have read and understood all parts of the documentation.

6.7. Device specific dangers



Danger to life due to electric shock

Depending on the variant, the product is operated with 230 V AC or 110 V AC.

- > Always check the supply line for damage before using the tool.
- In the event of damage to the supply line, the tool must not be used before it is profesionally repaired.
- > Repairs to the supply line may only be carried out by qualified electricians.
- Operation on construction sites may only be carried out by means of a power distributor with a residual current circuit breaker in accordance with VDE 0100.
- General as well as nationally and internationally valid safety guidelines and regulations for handling power tools must be followed.



Pull out the mains plug!

If you are not using the product, disconnect the power plug from the power source.

6.8. Residual risk

Despite all security measures a residual risk remains. Technically non-excludable risks are:

- > Grossly negligent handling of live wires and cables of the electrofusion control unit.
- > Intentional destruction of live wires and cables of the electrofusion control unit.
- > Risks due to subsequent technical modifications of the electrofusion control unit.

7. Scope of delivery



Note

The SmartFuse is available in different variants. The scope of delivery differs, depending on the ordered variant. Errata and technical modifications reserved!

Smarti	Fuse	Enclosed
1 ×	Instruction manual	DE002
1 ×	USB stick	5_5001_512
1 ×	Bluetooth dongle	2_5100_006
1 ×	Transport box	1_2800_072

A Flightcase is available as alternative to the transport box.

8. Technical data

	SmartFus	se		
General				
Output voltage	[V]	40 AC		
Data recording		Yes		
Power (60 % ON time) according to ISO 12176-2		2050 W (55.9 A)		
Operating temperature range	[°C]	-10 to +50		
International protection		IP54		
Appliance class		1		
Conformity		CE		
ISO 12176-2 Class - classification		P ₂ 3 U S ₁ F A D M		
Input of welding parameters				
SmartFuse				
Input/Mains		230 V devices	110 V devices	
Nominal voltage (tolerance)	[V]	230 AC (190 to 300)	110 AC (90 to 150)	
Nominal frequency (tolerance)	[Hz]	50/60	0 (40 to 70)	
Power factor cos ρ		0.6 to 0.9 (ph	nase-angle control)	
Nominal current	[A]	16	35	
Power consumption	[VA]	3680	3680	
Length of cord	[m]	4.5	On request	
Plug type		Euro Schuko plug, others on request	On request	
Output				
Output voltage	[V]	40 AC		
Output current (max.)		110		
Output current (t $\rightarrow \infty$)	[A]	30		
Output current (min.)	[A]	2		
Energy adjustment		None		
Welding cable length	[m]	5, other lengths on request		
Welding cable installation		Detachable		
Welding terminals	[mm]	4.0 (or universal terminals for 4.0 an	d 4.7)	
Monitoring functions				
Input		Voltage, current, frequency		
Output		Voltage, current, resistance, contact	, short circuit	
Other		System, Working Temperature, Serv	rice	
Error messages	or messages Plain Text, Acoustic Signal			
Casing/Display				
Material		Steel plate with plastic frame		
Display		4×20 Characters (alphanum.), backg	ground lighting	
Dimensions, weights and packaging				
Product dimensions L×W×H	[mm]	400×300×260		
Product weight (incl. welding cable)		17		
Packaging type		Flightcase	Wooden box	
Packaging material		Aluminiumframe with composite woo	od Wood	
Packaging dimensions L×W×H	[mm]	470×380×370	440×340×310	
Packaging weight	[kg]	7.5	3.6	
Transport weight	[kg]	25	21	

Technical file according to ISO 12176-2		
Classification		
Device type	SmartFuse	
Classification P2 3 U S1 F A D M		
Duty evels according to ISO 12476 2 at 20 % S0 % and 100 % Toot time t = 50 minutes		

Test time 60 min 60 min	Power at U _{OUT} = 36 V	Power at U _{OUT} = 40 V	Output current I _{OUT}
30 %	2700 W	3000 W	74.1 A
60 %	2050 W	2250 W	55.9 A
100 %	1600 W	1800 W	44.7 A

Additional Information		
Soft Start	At least 3 seconds (ramp)	
Ambient temperature compensation No		
Fitting temperature compensation	No	
Data recording	Yes	
Bluetooth LE Bluetooth LE		

The given technical information is valid for the standard setup of the electrofusion control unit. Depending on the ordered setup there may be variations.

8.1. Data recording

When using the SmartFuse app and connecting via Bluetooth, the electrofusion control units transmit logs to a connected smartphone or tablet. The SmartFuse electrofusion control units have a report storage capacity of approximately 1000 welds.

	SmartFuse		
Data recording			
Number of reports	Approx. 1000		
Interface	USB stick		
Data format	PDF, CSV		
Recorded data			
General data	Time, date, report number, ambient temperature, welder name, job number max. 40-digits (alphanumerical)		
Fusion data	Voltage, current, energy, nominal and actual welding time, mode, resistance, error messages with 10 voltage and current values		
Fitting data	No		
Device data	Serial number, inventory number, date of last service, working hours, system configuration		
Worker code	No		
Additional functions			
Output options	Whole memory, selectable by job number		
Job code input/selection	Manual, internal list of job numbers for selection		
Input of position data / free text	40 characters, per joint		

9. Input of welding parameters

The electrofusion control units of type SmartFuse provide the following means for entering the welding parameters:

9.1. SmartFuse-System*



By reading out the reference resistor in one of the connector pins of the SmartFuse-fitting the control unit automatically determines the welding parameters for the fitting.

10. Range of fitting dimensions

The range of fitting dimensions for which an electrofusion control unit can be used depends essentially on the power consumption of the used fittings. Since the power consumption of the fittings is different for different fitting manufacturers, it is not possible to provide a general rule which covers all the possible fitting dimensions. When in doubt, each fitting size must be checked separately.



Attention!

For electrofusion control units of type SmartFuse when all welding work is performed successively, such that the control unit has pauses in welding that correspond to the preparation time of the next fitting, the following rule applies.

The duration of the pause after each weld must be at least equal to the preparation time for the next welding joint. When you allow only shorter pauses, the electrofusion control unit is put under heavy load and can therefore heat up so much, even when welding smaller fittings, that a longer pause must be allowed for cooling down.



Attention!

For welding of couplers in with a welding time of ≥400 s a stable and continuous supply voltage of 230 V is mandatory. When using a generator, it must be set to a no load voltage of between 240 V and 260 V. The SmartFuse electrofusion control units can only be used together with SmartFuse-capable fittings.

The following table shows example values of the cooling time to be expected after each weld to ensure continuous operation. The table contains guide values and recommendations, as exact statements cannot be made due to the numerous influencing factors.

Fitting	Requirements
20 s to 600 s	Usable without restrictions.
750 s to 900 s	Longer cool-down times must be provided for because otherwise the device might show the "Device too hot" error message. In this case, it is necessary to let the electrofusion control unit cool down before putting it to use again.
>900 s	Only couplers that have a welding time of 900 s or below can be welded.



Attention!

Before processing fittings in this dimension range, you have to check that the welding current demand of the fitting does not continuously exceed the output current of the device and that the maximum output current is not exceeded.

The statements made above are made under the assumption that the ambient temperature is 20 °C.

11. Bluetooth functionality

The electrofusion control units of type SmartFuse can be equipped with an optionally available USB Bluetooth dongle. This allows the welding process to be controlled and recorded together with the SmartFuse app.

The app for smartphones and tablets is available for Android in the Google Play Store and for iOS in the Apple App Store. When using Bluetooth, the electrofusion control unit can only be used together with this app.



Attention!

To be able to use the app with the electrofusion control unit it is mandatory to have a registered account. Please ask your distributor.



Attention!

If the Bluetooth function in your electrofusion control unit is provided via a Bluetooth dongle, then the dongle must be inserted into the USB interface before switching on electrofusion control unit.

12. Spare parts and accessories

Description	Code
Terminal contact 4.0 M8 SmartFuse	2_0200_008
Terminal contact 4.0 M8	1_0200_008
Universal terminal, SmartFuse	2_0200_051
Universal terminal, standard	2_0200_052
Adapter 4.0 to 4.7 angular	2_0300_004
Adapter 4.0 to 4.0 angular	2_0300_011
Adapter SmartFuse 4.0 to 4.7	2_0200_007
Adapter 4.0 to 4.7, straight	2_0300_010

13. Transport, Installation and removal, storing



Qualification of personnel

The product may only be transported, installed, removed and stored by persons with relevant professional experience and expertise in using the product.



Safety

User and operator are responsible. Observe all safety instructions in this instruction manual as well as all valid safety regulations.

13.1. Transport damage

Check the product for damage immediately upon receipt. If damage or abnormalities are present, ideally document them with pictures and contact the manufacturer or your dealer.

13.2. Packaging

The product is integrated into its transport suitcase.



Damage to the packaging

Damage to the packaging may indicate damage to the product. If in doubt about the condition of the product, contact the manufacturer or your dealer.

13.3. Assembly and installation

Conditions for the installation site

- Make sure you have enough space and good lighting.
- The electrofusion control unit must be kept in a dry place.
- If necessary, set up a tent to protect the work area and the electrofusion control unit from the effects of the weather, such as strong sunlight, rain or moisture.
- The electrofusion control unit should not be operated in its transport container. (Exception: portable units built into suitcases)

Space requirements

The electrofusion control unit should stand freely to ensure the best possible heat dissipation.

13.4. Storage

Store the product in its transport container, protected from the weather. The temperature should be between 5 and 25 °C with a humidity of not more than 60%.

14. Connection to the power supply

14.1. General



NOTE

Country-specific connection regulations
GERMANY The conditions for connecting the electrofusion control unit in this instruction manual, the technical connection regulations of the local power supply company, the VDE regulations, the regulations for accident prevention as well as other DIN/CEN regulations in force must always be observed.

OTHER COUNTRIES: It is mandatory to observe the connection regulations for the electrofusion control unit in this instruction manual as well as all international and national health and safety regulations and the respective technical connection regulations in force.

Electrofusion control units may only be used by trained and, according to national and international standards, certified personnel.

The user must supervise and observe the electrofusion control unit during the whole welding procedure.

The electrofusion control unit must only be operated within the following operation ranges:

	230 V devices	110 V devices
Input voltage:	190 V to 300 V (AC)	90 V to 150 V
Input Frequency:	50/60 Hz (40 to 70 Hz)	50/60 Hz (40 to 70 Hz)
Ambient temperature:	-10 °C to +50 °C	-10 °C to +50 °C
Minimum Fuse/ Circuit breaker rating	16 A (slow)	40 A (slow)



Attention!

Operation of the electrofusion control unit is only allowed if a properly dimensioned and intact RCD is used. The information for proper fuse protection in the circuit are shown in the table above.

The electrofusion control unit's mains supply cord as well as any extension cords must be fully unwound prior to usage.

14.2. Extension lines



Attention!

The extension cords must provide a protective earthing contact.

It is forbidden to extend the welding cable.

Always observe all international and national legislation and guidelines for extending mains supply cords.

14.2.1. General

The mains supply cord shall only be extended in accordance with the following specifications.

Line length	Cross Section (230 V)	Cross Section (110 V)
Up to 20 m	3×1.5 mm²	3×4 mm²
20-50 m	3×2.5 mm²	3×4 mm²
50-100 m	3×4 mm²	-

14.2.2. For Australia

The extension of the mains cable may only be carried out with approved extension cables. These can be obtained on request from your local distributor of electrofusion control units made by PF-Schweißtechnologie GmbH.



Attention!

- For electrofusion control boxes used in Australia only extension cords acknowledged and approved by PF-Schweißtechnologie GmbH, a local distributor or an official PF service station shall be used.
- Using a non-approved extension cord is a health safety risk.
- > Using a non-approved extension cord voids the manufacturer's warranty on the unit.

14.3. Generator compatibility



Important notes for the usage together with generators!

- AUSTRALIA: Ensure that the generator is regularly inspected, tested and tagged by a licensed electrician or other competent person in accordance with workplace health and safety legislation and national standards.
- > The generator must be grounded!
- > The outlet which the electrofusion control unit is used together with must have a protective earthing conductor!
- It is very important that there is a Protective Earthing (PE) conductor which is continuous (i.e. <0.5 Ohms) from the earth terminal of the generator to the earth terminal of the plug on the flexible supply cord of the electrofusion control unit. If the protective earthing conductor is interrupted or becomes higher in resistance, there is a risk of electric shock. For this reason, always ensure that only extension cords of the approved type are used. Ensure that the electrofusion control unit, all accessories and extension cords are regularly inspected, tested and tagged by a licensed electrician or other competent person.</p>
- First start the generator, then plug in the electrofusion control unit.
- > No other machine or device must be connected to the generator.
- > 400 V devices: The open circuit voltage should be set between 415 V and 430 V.
- > Unplug the mains supply cable of the electrofusion control unit before turning the generator off.
- > The usable generator power will decrease by 10 % per 1000 m of height above sea level.
- > Check the fuel level before starting the welding process.
- > The instruction manual of the generator as well as its operating instructions are part of this instruction manual. Always read them carefully!

The electrofusion control units of type SmartFuse provide the following features to increase the generator suitability:

- > High tolerance for the input voltage
 - > 190 V to 300 V at 230 V nominal
- > High tolerance for the input frequency
 - ➤ 40 Hz to 70 Hz
- Display of current input voltage and frequency.
- Soft-Start for limitation of the generator load.

Despite these characteristics, the used generators must meet the following requirements and recommendations, in order to avoid damage to the electrofusion control unit. This ensures that the internal monitoring functions of the control unit do not interrupt the welding process:

- Suitable for phase-angle control and able to drive inductive loads
- > 230 V:
 - No-load voltage adjustable between 240 V and 260 V
 - Output current of 18 A on one phase
- > 110 V:
 - ➤ No-load voltage adjustable to 120 V 130 V
 - > Output current of 36 A on one phase
- > Stable output voltage and engine RPM even with rapidly changing load
- Synchronous generators with mechanical RPM control preferred
- Voltage peaks must not exceed 800 V

14.3.1. Required generator rated output power



It is not possible to make a statement for the necessary generator output power in each individual case, because every fitting manufacturer has different specifications.

The information in the following table below is to be used only as a guide as it can differ from your actual requirements.

The usable generator power will decrease by 10 % per 1000 m of height above sea level.

Fitting diameter	Output Power
20-160 mm	3.2 kW
180-500 mm	4.5 kW (mechanically controlled) 5 kW (electronically controlled)
	6.5 kW (mechanically controlled) 7.5 kW (electronically controlled)

For generators with a poor control response or for generators with a bad tension stability, the guaranteed output power must be 3 to 3.5 times of the load to ensure a trouble free operation. The suitability of electronically controlled generators must be tested before usage due to the fact that the rotational speed of some generators tend to fluctuate, which results in extreme voltage peaks. Furthermore unexpected shutdown of the generator may occur.

15. Preparation of a welding procedure

The electrofusion control units SmartFuse only offer SmartFuse as a means for input of welding parameters.



Attention!

- > The generator must be grounded!
- If the electrofusion control unit is used on a generator which is not grounded or on mains without protective earthing conductor there is a risk of an electric shock.



Qualification of personnel

All persons involved in the assembly and installation must have read and understood this instruction manual and in particular all safety instructions.



Important information about your safety

You are responsible!

All safety instructions in this instruction manual and the generally applicable measures for accident prevention must be adhered to.

Requirement:

! The safety instructions are observed.

15.1. General checks and measures before usage

- ! Check the electrofusion control unit, cables and adapters optically and replace them in case of defects or damage.
- ! The welding cables, mains cable and extension cables must be completely unwound.
- ! Connect the detachable welding cable to the control unit.
- ! Switch off the ON-OFF-switch of the electrofusion contol unit.
- ! Start the generator before plugging in the electrofusion control unit. Wait until the generator output voltage has stabilized.
- ! Plug in the power cord of the electrofusion control unit.

15.2. Switching the electrofusion control unit on

- 1. Switch the ON-OFF-switch to "ON" position.
- The electrofusion control unit signals its readiness by two bleeps. The background lighting of the display turns on automatically. The display shows the following message for approx. 5 seconds.

SmartFuse 2.40H5

0 Workings hours

Type Software version Working hours

Display after switching on

15.2.1. Other display messages

After the startup display is shown, other messages might be displayed before the main display is shown.

15.2.1.1. System config. at last welding process

If the system configuration is changed before the next restart of the electrofusion control unit, a message in the display is shown which indicates, that the system configuration has been changed and what was changed. This is also stored in a report.

This message is acknowledged by pressing the red stop button.

15.2.1.2. Error occurred

If an error during or before the last welding has occurred (for example resistor error), a special message will appear in the display as a reminder.

> This message is acknowledged by pressing the red stop button.

Example

The following example is meant to show how the device will indicate that an error has occurred before switching the electrofusion control unit off.

Resistance error during last Welding Error message

Display after switching on



General remark

These messages do not show current errors/problems. They are only meant to remind the user that an error/ problem occurred before the electrofusion control unit was switched off the last time!

The message is displayed each time after the electrofusion control unit is switched on until a successful weld has been performed.

15.2.1.3. Service

This message is displayed as soon as the service interval has passed. This can happen, if the set time for the service interval (e. g.12 months) has passed, or, for electrofusion control units with no data recording, after 200 operating hours.

This message is acknowledged by pressing the red stop button.



Attention!

It is recommended to send the electrofusion control unit in for service as soon as this message appears. The display of this message is a recommendation or reminder to you, that the service interval of the electrofusion control unit is reached. The display of this message does not mean, that the electrofusion control unit cannot be used anymore before service.

By acknowledging with a press on the red stop button the electrofusion control unit switches back to the main display.

15.3. Pairing via Bluetooth



Attention!

- With electrofusion control units made by PF-Schweisstechnologie GmbH the Bluetooth function is only available if either the unit itself has a built-in Bluetooth module or if the optionally available Bluetooth dongle is plugged into the USB interface.
- To use the Bluetooth connection, the option "BT on" must be activated in the system configuration of the electrofusion control unit.
- Pairing is possible only when using the app of the manufacturer of the electrofusion control unit. To use the app and its functions a registration is mandatory. For further information please contact your distributor or PF-Schweißtechnologie GmbH.
- Insert the Bluetooth dongle before switching on the electrofusion control unit. Only then will the unit recognise that it is plugged in.
- Do not manually pair your smartphone or tablet with the electrofusion control unit. Start the EFCC/SmartFuse app when the electrofusion control unit displays "Waiting for app". Only pair the device via the app when prompted to do so. If you have already manually paired the electrofusion control unit with your device before, disconnect the pairing. Pairing only works if it is done via the app.



Attention!

If the Bluetooth function in your electrofusion control unit is provided via a Bluetooth dongle, then the dongle must be inserted into the USB interface before switching on electrofusion control unit.

15.3.1. Option "BT on" active, "BT only" inactive

Display after switching on, if "BT on" is active

The electrofusion control unit shows the following display. You can now pair your device with the electrofusion control unit via the app.

#10020981 ↓Menu Waiting for App STOP Cancel Identifier of the device to find it via Bluetooth.

The unit is waiting to be paired via the EFCC app.

Device is waiting for Bluetooth pairing

- → Press the enter button to enter the system settings. Depending on the setting ("Code Sys" on or off), you need an administrator code to be authorised to access the system.
- → Press the red stop button to cancel the pairing and continue without Bluetooth.

15.3.2. Option "BT on" active, "BT only" active



Attention!

With these settings, the unit can only be used via the EFCC app.

Display after switching on, if "BT on" and "BT only" are active

The electrofusion control unit shows the following display. Now you can use the app to pair the electrofusion control unit with your mobile device.

#100209812 ?Menu Waiting for App BT only Identifier of the device to find it via Bluetooth.

The unit is waiting to be paired via the EFCC app.

Work only possible via EFCC app.

Device is waiting for Bluetooth pairing

→ Press the enter button to enter the system settings. Depending on the setting ("Code Sys" on or off), you need an administrator code to be authorised to access the system.

15.3.3. Pairing via Bluetooth is finished

#100209812 ?Menu Waiting for App CONNECT

Pairing was successful.

Display after pairing

→ Now continue to operate the controller using the "ElectroFusion Studio" app on your mobile device.

#10020981 dMenu
Waiting for App
BT active

Operation via smartphone/tablet.

Display after pairing



Attention!

When using the EFCC app, the entire welding process is controlled by the app.

15.4. Main display

If no fitting is connected, the electrofusion electrofusion control unit shows the main display.

Connect SmartFuse Voltage: 230 V Frequency 50 Hz No contact

Request to connect a fitting.

Mains voltage Mains frequency

No fitting connected.

Main display

- → Press the enter button to enter the system settings.
- → Press the right arrow button ▶ to display device data.
- → Connect a fitting to start the welding process.

15.5. Displaying device data

Displaying device data

When the main display is shown you can display device data of the electrofusion control unit by pressing and holding the ▶ button.

Connect SmartFuse		
Voltage:	230	V
Frequency	50	Ηz
No contact		

USB 1 oth Clock N S Ver: 8 +20 C 236V 50Hz 1.0V 1.86A

Main display

Line	Item	Description
1	USB 1	The USB controller was detected.
1	USB 0	The USB controller was not detected.
1	oth	The USB Bluetooth dongle is plugged in.
1	No	The USB Bluetooth dongle is not plugged in.
1	Clock N	Setting of the clock to the northern hemisphere.
1	Clock S	Setting of the clock to the southern hemisphere.
•	Olook o	County of the clock to the county homophere.
1	S	Summe time
1	W	Winter time
2	Ver: 8	Version of the USB chip
	+20 C	Ambient temperature
3	236 V	Present supply voltage
	50 Hz	Present mains frequency
4	1.0 V	Display of the present voltage between the welding terminals
	1.86A	Display of the last measured current

[→] Depending on the model, further data such as the total welding time of the unit, the inventory and device number as well as the software version of various hardware components can be displayed by pressing the arrow keys ▲ ▼.

[→] Press the red stop button to exit the display of device related data and return to the main display.

Performing the welding process

16.1. Important information



Note

The contact surfaces of the welding terminals and the pins of the fitting must be clean. Dirty or coated terminals lead to overheating and scorching on the areas of contact inside the welding terminals. The welding terminals must be replaced as soon as they develop a coating on the contact surfaces or a loss of contact force is noticeable.



Attention

- Pay attention to the installation instructions of the fitting, special instructions (ISO, CEN, DVGW, DVS), European and national directives as well as to the instructions of the manufacturers.
- After the welding parameters have been automatically determined it is imperative that you cross check the displayed parameters with the ones shown on the fitting to make sure, that the correct welding parameters are used.

16.2. Connect Fitting

No fitting connected

→ If no fitting is connected, the electrofusion electrofusion control unit shows the main display.

Connect SmartFuse
Voltage: 230 V
Frequency 50 Hz
No contact

Request to connect a fitting.

Mains voltage
Mains frequency
No fitting connected.

Main display

→ Connect a SmartFuse fitting to start the welding process.

16.3. Welding with SmartFuse



Note

To weld with the SmartFuse system the red terminal must be connected to the contact of the fitting that bears a red marking. After a fitting has been connected correctly in this manner, the electrofusion control unit begins to determine the welding parameters based on the built-in resistor in the contact of the fitting.

- ! A SmartFuse capable fitting is connected.
- During the measuring process, the display shows the following message. The welding parameters are determined.

SmartFuse measure 231V 50Hz +26 C 10.05.2019 11:12:00 10 SmartFuse resistor is read out.

Mains voltage
Mains frequency

Display when SmartFuse measurement is active

After the welding parameters have been determined, the electrofusion control unit shows the following information in the display.

Start Welding time 30 s PLAS 40V

Detected welding time
Fitting manufacturer and welding voltage

Display of the determined welding parameters



Attention

It is imperative that the parameters displayed match the parameters written on the fitting by its manufacturer

3. To start the welding procedure with the displayed parameters press the green start button.

16.3.1. Reminder to clamp the pipes

→ After pressing the green start button a message will remind you of your duty to fix and prepare the pipes according to the general guidelines.

Is the pipe scraped and clamped

Reminder

- → Press the green start button to confirm proper preparation.
- → By pressing the red stop button you can cancel the procedure.

Measuring the fitting resistance

The electrofusion control unit begins to measure the fitting resistance. Should the measured fitting
resistance be out of the valid range, an error message will be shown on the display and the error will
be indicated by a bleep. The bleep can be interrupted by pressing the red stop button.

0.15< 0.05 <35.00 Nominal time: 30 s

Range limits and measured resistance

Nominal welding time

Resistance error

Error message

Display when a resistance error has occurred

Unplug the welding cable from the fitting. Check that the contacts of the fitting and the welding terminals are clean. Should the fitting, after cleaning the contact surfaces, produce another resistor error then it could be defective. Use another fitting.

No resistance error detected

The electrofusion control unit begins the welding procedure automatically if no resistance error occurred



Attention

Do not touch the fitting or the contact surfaces during the welding process. Keep a minimum safe distance of 1 m to avoid the risk of injury by molten PE mass.

16.3.2. During the welding procedure

→ The display shows the actual and nominal welding time:

Actual time: 1 s Nominal time: 30 sPLA 40 V

Passed actual time

Nominal welding time

Specification of the fitting

Line for possible error messages

Display during the welding procedure

16.3.3. After the end of the welding procedure

1. The welding process will stop automatically when the actual time reaches the nominal time. This will be indicated by two bleeps and the following message:

Actual time: 30 s Nominal time: 30 s OK Display after the welding procedure

Passed actual time

Nominal welding time

Line for possible error messages

2. After completion of the welding procedure, the welding terminals can be unplugged cautiously from the fitting. This will take you back to the main display.



Attention

- > Do not forcefully remove the welding terminals from the fitting.
- > Before transporting the electrofusion control unit, unplug the welding terminals from the fitting.
- > Observe the cooling time, the processing instructions as well as the processing guidelines of the fitting manufacturer as well as those of the pipe manufacturer.

OPTIONAL: Display of weld-related data

1. After completion of the welding procedure, the following information of the welding can be displayed by keeping the A-button on the keypad pressed.

2.25 Ohm 40 V 10.596 kJ 10.05.2019 11.12

Measured resistance before the start in Ohm (Ω)

Nominal voltage in Volt (V)

Energy input in kilojoules (kJ)

Date and time

Display of additional data on the completed weld


2. By pressing the enter button you can return to the main display.

17. Function menu

The menu contains a list of all available functions. The symbol < is the selection indicator that marks the entry that is selected or activated when the enter button is pressed.

Displaying the function menu

1. Press the enter button while the main display is shown or while you have contacted a fitting.



>Contrast USB Erase reports

Main display

Function menu

- 2. The function menu is shown.
- → Use the arrow buttons ▲ ▼ to move the selection indicator < up and down.
- → Use the enter button to open the entry marked with the selection indicator <.
- → Press the red stop button to cancel and return to the main display.

The following table shows the available functions.

Functions	Description	
Job no.	Entering a job number (commission number)	
USB	Data transfer to a USB stick	
Erase reports	Erasing the reports per job number	44
Contrast	Setting of the display contrast	45
Volume	Setting the volume of the signal horn	46
System configuration	System configuration options	47

17.1. Using the letter field to enter data

To manually enter data a letter field will be displayed. Using the letter field to enter letters or digits is always done in the same way, which is why it is presented here comprehensively.

Using the letter field to enter data

ABCDEFGHIJKLMNOPQRST UVWXYZ0123456789 \$-/ First row for the input
Second row for the input
Available letters and numbers
Available letters and numbers

Letter field

The first two rows display the letters and numbers that have been entered. Depending on the function a default string may already be set. The last two rows list all available letters and numbers.

1. Entering a string of characters

When you begin, the first position is marked. The mark is indicated by flashing. Move the cursor (star *) under the character you want to enter by pressing the arrow buttons ◀ ▲ ▼ ▶. Enter the selected character using the enter button. The selected and entered character appears in the first row of the display at the flashing position. Enter all desired characters one by one.

2. Editing a string of characters

If you want to change a specific position in the displayed character string, move the selection indicator out of the letter field with the arrow button ▲. The star * disappears and you can move the flashing cursor by pressing the ◀ and ▶-buttons to any position in the already entered string. To change the marked character push the enter button to get the star * back in the letter field and proceed as described under 1).

3. Finishing the input

Finish the input of the string by pressing the green start button. Alternatively, you can leave the letter field by pressing the red stop button to cancel the entry. In this case, your input will not used for the following process.

17.2. Job no.

In this menu you can select a job number under which the following reports will be stored. Alternatively you can create a new job number with the help of a letter field. The job number may have a maximum of 40 characters.

17.2.1. Entering a job number (commission number)

- 1. Use the arrow keys ▲ ▼ to select the "Job no." entry in the function menu.
- 2. Then press the enter button to select the function.
- 3. The currently active job number is shown in the display.

+++++Job number+++++

Text of the job number

ABCDEFGHIJKLMNOPQRST UVWXYZ0123456789 \$-/ Available letters and numbers Available letters and numbers

Letter field

- → Use the arrow buttons **A V** to switch to the already existing job numbers.
- → Use the arrow buttons **♦** to move the flashing marker.
- → Press the red stop button to cancel and return to the main display.
- → With the green start button you set the displayed job number active.

17.2.2. Creating a job number (commission number)

4. When the flashing highlight is on a character that you want to change, press the enter button to move the highlight to the letter selection.



Note

When opening a job number, the input marker is already in the letter field. You can directly overwrite the first character. If you want to edit another character, bring the flashing selection into the text by pressing the arrow button \blacktriangle .

- Use the arrow buttons ◀▲▶▼ to select the character you want to enter in the letter field and press
 the enter button
- The flashing selection automatically jumps one place further. Continue typing until you have entered
 the desired string. If you want to move the flashing selection during input, press the arrow button ▲
 until it appears in the text above.
- 7. Press the green start button to save the new job number. This is then set as active.

17.3. USB

Under the menu item "USB" you can transfer reports to a USB stick.



Note

Before selecting the menu item "USB", connect the USB stick to the USB interface of the electrofusion control unit.

After selecting the menu entry "USB" the electrofusion control unit checks if a device is connected. If this is not the case, an error will be shown.

Function	Memory	Appearance in PDF
All (short)	Whole memory (all reports)	Tabulated
All (long)	Whole memory (all reports)	1 page per report
Job no. (short)	Per job number	Tabulated
Job no. (long)	Per job number	1 page per report

When transferring the reports to a USB stick two files are created: one PDF file and one file with the extension "log", which contains the reports in CSV format.

PDF-Format

The electrofusion control unit generates a PDF file on the USB stick, which records the already formatted welding records. The PDF file can be opened with Adobe Acrobat Reader (Version 3.0 or higher; www.adobe.com).

CSV-Format

This format contains the report data in a tabular format, in which the report data is stored in one row each. The data fields are separated by semicolons. This file type can be opened by standard spreadsheet or database applications. However, we recommend that you use the EXCEL macro stored on the USB stick to import the data unaltered into an Excel spreadsheet. The macro is located on the enclosed USB stick in the directory </macro/en>. Also, read the manual for this macro, which is stored in the same folder. In addition, the content of the folder should be copied to a computer and the EXCEL macro should only be run from a local hard drive.

The CSV file can also be opened with the Datamatic software. To do so use the function "Open as text file" and select the appropriate file.

Storage location/Filenames: The electrofusion control unit creates a subdirectory </PFS> on the USB stick where the created files are saved. The file names are generated by the electrofusion control unit according to the following syntax: <PFnnnnn.PDF> for PDF files and <PFnnnnn.log> for CVS-files. <nnnnn> stands for an incremental numbering, which ensures that already existing files are not overwritten.



Attention

The USB flash drive is not suitable for permanent storage of data. Backup your data regularly.

17.3.1. Transfer reports to a USB stick



Attention

The functionality of the USB data transfer can only be guaranteed for the supplied USB stick.

If you use a different USB stick, it should match the following specifications to increase the probability of being compatible:

Storage capacity: max. 1 TB File system: FAT32

- 8. Insert the supplied USB stick into the USB interface of the device. If you are using another USB stick, make sure that it is not write-protected.
- 9. Use the arrow keys ▲ ▼ to select the "USB" entry in the function menu.
- 10.Then press the enter button to select the function. After that, a display with the available printing options is shown.

The menu "USB"



Display in the "USB" menu

- → Use the arrow buttons **A V** to move through the menu items.
- → Use the enter button to start the operation marked with the selection symbol <.
- → Press the red stop button to cancel and return to the main display.
- Make your selection here. You can choose if you want to print all reports or only those that are stored
 under a certain job number. Navigate to the desired entry by pressing the ▲- and ▼- buttons and
 confirm the selection by pressing the enter button to begin data transfer.
- If you chose to transfer the reports per job number, select the respective job number with the arrow buttons ▲- and ▼ and confirm your selection with the green start button.
- 3. The data transfer begins. During data transfer, the following message appears in the display. (The data shown here are but an example and are different depending on the conditions.)

Data transfer PF000006.PDF

File name

Dots appear when the last file is created

Display during data transfer

4. After successful data transfer the following display will be shown, if you chose to transfer all reports. This query does not appear in the case of job number-dependent transfer.



Prompt for deletion after the data transfer

OPTIONAL: Deletion of the transferred reports

The prompt "Erase?", which is shown if all reports were transferred, makes it possible to delete all reports in the electrofusion control unit.

- If you want to erase the reports, press the green start button. A confirmation prompt "Are you sure?" will be displayed.
- 6. If you confirm this prompt by pressing the green start button, the respective reports will be erased. The display then shows the function menu again.

OPTIONAL: Leaving the transmitted reports in the device's memory

7. If you do not want to delete the reports and leave them stored in the memory of the device, press the red stop button. The display then shows the function menu again.



Note

The prompt for deletion of the transferred reports only appears if "Secure data" is deactivated in the system configuration.



Attention

To avoid possible errors in the memory management or loss of data, ensure that the electrofusion control unit is not cut off from power during deletion of the reports. This could lead to the destruction of the electronics!

NEVER switch the electrofusion control unit off during the deletion of welding reports.

17.4. Erase reports

This function enables you to delete the reports that are stored in the electrofusion control unit. The reports can be deleted per job number. You can press the red stop button at any time. This will take you back to the main display.



Note

You can lock this option so that you are prompted for an access code when trying to access it. Refer to the chapter "Code Del." of the system configuration.



Attention

If you erase the reports of one job number then you will automatically delete the job number from the memory of the device. If you still need the respective job number, you must enter it again after the deletion.



Attention

To avoid possible errors in the memory management or loss of data, ensure that the electrofusion control unit is not cut off from power during deletion of the reports. This could lead to the destruction of the electronics!

NEVER switch the electrofusion control unit off during the deletion of welding reports.

- 1. Use the arrow buttons ▲ ▼ to select the "Erase reports?" entry in the function menu.
- 2. Then press the enter button to select the function.



Locking

entered code.


You can lock this option so that you are prompted for an access code when trying to access it. Refer to the chapter "Code Del." of the system configuration.

If you have locked the erase function by activating the "Code Del." option in the system configuration you will be prompted for an administrator code. Such an administrator code can be found at the end of this manual. You can also obtain an administrator code on request from your dealer or the manufacturer. Read in the administrator code using the reading pen/scanner or press the enter button to enter the code by using the letter field. If you use the letter field, press the green start button after the input to confirm the

If you have not locked the erase function in the system configuration ("Code Del." is deactivated by default) a display with job numbers will be shown after pressing the enter button.

The menu "Erase reports"


3. The following display is shown.



Display in the menu "Erase reports"

Erasing of reports that are stored under the selected job number

- 4. Select the job number that you want to erase and press the green start button.
- 5. After you have pressed the green start button, the following display will be shown.



Display in the menu "Erase reports"

- → Press the green start button to confirm the "Erase?" guery.
- → Press the red stop button to cancel and return to the main display.
- 6. Confirm the following safety prompt "Are you sure?" by pressing the green start button. The reports stored under the job code are erased and the job number is erased from the memory of the electrofusion control unit.

17.5. Contrast (Display)

This function enables you to adjust the display contrast to the lighting condition in your work area.

- 1. Use the arrow buttons ▲ ▼ to select the "Contrast" entry in the function menu.
- 2. Press the enter button to select the function.



Values between 100 and 4000

Setting of the contrast

- → Use the arrow keys ▲ ▼ to set the desired value for the contrast.
- → Press the green start button to confirm the entry.
- → Press the red stop button to cancel and return to the main display.
- 3. When you have changed the contrast value, confirm this by pressing the green start button.

17.6. Volume

With this function you have the possibility to adjust the volume of the signal horn in three stages. The default setting is high.

- 1. Use the arrow buttons ▲ ▼ to select the "Volume" entry in the function menu.
- 2. Press the enter button to select the function.



Setting of the contrast

- → Use the arrow keys **** ▼ to change to the desired volume.
- → Use the enter button to accept the selected volume.
- → Press the red stop button to cancel and return to the main display.

18. System config.

In the menu "System config." different settings and functions of the electrofusion control unit can be changed. Depending on the basic configuration of the device, it is possible that an unlocking- resp. administrator code is required to gain access to this menu. This restriction can be deactivated in this menu.

Accessing the system configuration


- 1. Use arrow buttons ▲ ▼ to select the entry "System config." in the function menu.
- 2. Press the enter button to select the function.



Menu is locked

If the "Code Sys." option is activated in the system configuration, a prompt for an administrator code appears when you try to access the system configuration. Scan a corresponding code to access the "System config." menu. Such an administrator code can be found at the end of this manual. You can also obtain an administrator code on request from your dealer or the manufacturer.

The system configuration



System config.

- → Use the arrow buttons A ▼ to move the selection indicator < up and down.</p>
- → Use the enter button to open the entry marked with the selection indicator <.
- → Press the green start button to accept and save the current values and return to the main display.
- → Press the red stop button to cancel and return to the main display.

18.1. Menu navigation

The electrofusion control unit has numerous functions that can be activated and deactivated without a submenu.

- → Use the arrow buttons ▲ ▼ to move the selection indicator < up and down.</p>
- 1. Press the enter button to change the status of the option.
- → A + means that the option is active.
- → A means that the option is inactive.
- To save the setting, confirm your entry and the subsequent security prompt "Are you sure?" with the green start button.

The following table shows the available functions.

Functions	Functions Description		Page	
Language	Setting the display language	Short code for language	48	
Inv. number	Issuing an inventory number for the electrofusion control unit	Number	48	
Set clock	Setting of time and date	Time	49	
Update	Function for updating the device software via USB	-	49	
Memory control	Memory control	ON/OFF	49	
Daylight time	Automatic changeover for summer and winter time	ON/OFF	49	
Weldername	Prompt for a welder name after switching on the electrofusion control unit	ON/OFF	49	
Job no.	Mandatory input of a job number	ON/OFF	50	
South	Summer-/Winter time for the southern hemisphere	ON/OFF	50	
Cont. numbers	Consecutive numbering of the reports	ON/OFF	50	
Code Lock	Activate the locking functions of the controller	ON/OFF	50	
Code Sys.	Locking of the system configuration	ON/OFF	51	
Code Del.	Locking the option for erasure of reports	ON/OFF	51	
Secure data	Mandatory input of a code when trying to access report erasing function		51	
BT on	Switching Bluetooth on and off	ON/OFF	52	
BT only	Operation of the device only possible by app via Bluetooth	ON/OFF	52	

18.2. Language

- 1. A list of available languages appears.
- Use the arrow buttons ▲ ▼ to select the desired language and press the green start button to apply
 the setting. Confirm the following safety prompt "Are you sure?" by pressing the green start button.
- → Press the red stop button to cancel and return to the main display.

18.3. Inv. number

The inventory number can be defined to identify the electrofusion control unit in your stock. The inventory number can be defined to identify the electrofusion control unit in your stock. You can use the displayed letter field for input or use a barcode together with the reading pen/scanner. The entered inventory number will be shown on the reports.

- 1. Use the letter field for input of the desired inventory number.
- 2. A letter field appears for manual input of the inventory number. Enter the numbers of the inventory number here using the arrow buttons ◀▲▼▶ and the enter button.
- → With the green start button the entered inventory number is set active.
- → Press the red stop button to cancel and return to the main display.



Setup

By default the device number of the electrofusion control unit is set as inventory number.

18.4. Set clock

After selecting the set clock function from the system configuration menu the display will show the current time and date.

- 1. The flashing mark is on the first number.
- → Use the arrow keys **A V** to change the currently marked value.
- → Use the arrow keys < ► to move the flashing selection to the place you want to enter.</p>
- > Press the green start button to confirm the entry.
- → Press the red stop button to cancel and return to the main display.
- 2. Set the time and date accordingly.

To save the setting, confirm your entry and the subsequent security prompt "Are you sure?" with the green start button.

18.5. Update

The update function can be used to update the software of the device in case of a problem. This function is intended for trained personnel only. Should it be necessary to use this function in an exceptional case, you will receive support from your sales partner or PF Schweißtechnologie GmbH.

18.6. Memory control

When the memory control option is activated, the electrofusion control unit will not begin another welding procedure as soon as the internal memory is full. This can help to prevent an unintentional loss of data. In any case, you are warned by a display message when switching the electrofusion control unit on as soon as there less than 50 free report spaces available.

Press the enter button to change the status of the option.

18.7. Daylight time

With this option, you can activate or deactivate the automatic changeover for summer and winter time. If the automatic changeover is active on the 21st of March resp. on the 21st of October a prompt "Change time" will be shown each time the device is switched on. If the prompt is confirmed by pressing the green start button the respective changeover will be made. If you press the red stop button, the changeover will not be made and the prompt will reappear the next time the device is switched on.

- 1. Press the enter button to change the status of the option.
- To save the setting, confirm your entry and the subsequent security prompt "Are you sure?" with the green start button.

18.8. Weldername

If this function is activated, a prompt for entering a welder name is shown after switching on the electrofusion control unit. The can be entered with the help of the displayed letter field.

- 1. Press the enter button to change the status of the option.
- To save the setting, confirm your entry and the subsequent security prompt "Are you sure?" with the green start button.

18.9. Job no.

If this function is activated, a prompt for the input/selection of job number, under which the report will be stored, is displayed after connecting a fitting. The job number can consist of numbers and letters.

1. Press the enter button to change the status of the option.

To save the setting, confirm your entry and the subsequent security prompt "Are you sure?" with the green start button.

18.10. South

If this option is activated the automatic changeover between summer and winter time will be done like on the southern hemisphere. Deactivate this option if you are on the northern hemisphere.

- 1. Press the enter button to change the status of the option.
- To save the setting, confirm your entry and the subsequent security prompt "Are you sure?" with the green start button.

18.11. Cont. numbers

If this option is activated, the reports will be numbered consecutively. If this option is deactivated, the numbering for each job number begins at 0001.

- 1. Press the enter button to change the status of the option.
- To save the setting, confirm your entry and the subsequent security prompt "Are you sure?" with the green start button.

18.12. Code Lock

When activating this function the controller checks, if already activated locking functions (depending of the type of controller "Code Sys.", "Code Man.", "Code Del." and "Secure Data") are sufficient to ensure, that their deactivation can only be done after entering an administrator code to access the system configuration. That way an efficient security measure can be set to prevent, that locking functions can be easily deactivated (bypassed) in the system configuration.

If "Code Lock" is deactivated, the electrofusion control unit can be freely configured to your liking. It is then possible that, for example, "Code Man." can be activated without locking the system configuration by activating "Code Sys." as well.



Attention

This option can be preset, depending on the device type. Contact your retailer or the manufacturer of the electrofusion control unit before activating this option.

In any case you will need an administrator code for accessing the locked functions if this option is activated and "Code Sys." is also active.

- 1. Press the enter button to change the status of the option.
- To save the setting, confirm your entry and the subsequent security prompt "Are you sure?" with the green start button.



Note

Please note, that when activating this option, independently from other options that may already be active, "Code Sys." will automatically also be activated. This prevents, bypassing and deactivating of locking functions in the system configuration without an unlocking- or administrator code.

18.13. Code Sys.

If this option is activated, the system configuration can only be accessed after entering an unlocking- resp. supervisorcode. If this option is deactivated, each user can change the system configuration. By activating this option, only users with the respective access level can change the system configuration.



Attentior

This option can be preset, depending on the device type. Contact your retailer or the manufacturer of the electrofusion control unit before activating this option.

In any case you will need an unlocking- or administrator code for accessing the system configuration if this option is activated.

- 1. Press the enter button to change the status of the option.
- To save the setting, confirm your entry and the subsequent security prompt "Are you sure?" with the green start button.



Attention

If "Code Lock" and "Code Sys." are active and "Code Sys." is deactivated, "Code Del." and "Secure data" will be deactivated automatically as well.

This shall show the user that by deactivating "Code Sys." there will be no sufficient safeguard against manipulation anymore. Without the prompt for the administrator code before getting access to the system configuration the locking functions can easily be deactivated by any user.

18.14. Code Del.

If this option is activated you will have to enter an access code when trying to acces the "Erase reports" entry in the device menu.

- 1. Press the enter button to change the status of the option.
- To save the setting, confirm your entry and the subsequent security prompt "Are you sure?" with the green start button.



Attention

If "Code Lock" is active when "Code Del." is activated, "Code Sys." will be activated automatically. This ensures, that reports can only be deleted from the memory of the electrofusion control unit if an administrator code is entered beforehand. In addition, "Code Sys." prevents access to the system settings without an administrator code.

18.15. Secure data

If this option is enabled, then no prompt appears after the report transmission as to whether the reports just transmitted should be deleted. This prevents deletion by unauthorised personnel.

- 1. Press the enter button to change the status of the option.
- To save the setting, confirm your entry and the subsequent security prompt "Are you sure?" with the green start button.



Attention

If "Code Lock" is active when "Secure data" is activated, "Code Sys." and "Code Del." will be activated automatically.

This ensures, that reports can only be deleted from the memory of the electrofusion control unit if an administrator code is entered beforehand. In addition, "Code Sys." prevents access to the system settings without an administrator code.

18.16. BT on

If this option is activated, the electrofusion control unit can be detected by other devices via Bluetooth. Pairing with a smartphone or tablet that runs Android or iOS and is connected to the internet is now possible. After successful pairing you can control the electrofusion control unit by using the PFS app.



Attention

Without prior registration, the connection to the electrofusion control unit will not be possible.

- 1. Press the enter button to change the status of the option.
- To save the setting, confirm your entry and the subsequent security prompt "Are you sure?" with the green start button.

18.17. BT only



Attention

If this option is activated, the electrofusion control unit can only be controlled by the app via Bluetooth. To deactivate this option after a restart, you must have permission to access the system configuration.

- > If this option is enabled, the "Code Sys." option is automatically enabled as well.
- > If this option is enabled, the "BT on" option is automatically enabled as well.
- 1. Press the enter button to change the status of the option.
- To save the setting, confirm your entry and the subsequent security prompt "Are you sure?" with the green start button.

19. Maintenance and troubleshooting



Important information about your safety

You are responsible!

All safety instructions in this instruction manual and the generally applicable measures for accident prevention must be adhered to.

The product, its components and accessories must be handled with care and maintained regularly in order to achieve the best possible work result.





Maintenance work

All maintenance beyond the removal of simple mechanical disturbances, such as for example disassembling the product into its components, may only be performed by the manufacturer or an authorized service center within the first 24 months of purchase. If you are unsure whether you are allowed to perform a particular activity, please contact your dealer or the manufacturer.

For safety reasons, even after the expiry of the 24 months, we strongly advise that repairs and maintenance be carried out only by the manufacturer or an authorized service station.

Tampering with components of the product without prior consultation of your dealer or the manufacturer may compromise safety and is therefore considered improper use.

In all correspondence, please provide the serial number (S/N) as shown on the type plate of the tool.

19.1. Qualification of personnel



Maintenance and repair

Only personnel with user and specialist knowledge in handling the product may service this according to the specifications.



Cleaning

The personnel responsible for the cleaning must at least have read and understood the safety instructions. Furthermore, it is only necessary that the generally valid procedures and safety regulations are observed when handling power tools.

19.2. Maintenance by laymen

Laymen should not perform any work on the product without the supervision of experienced people or professionals. Under supervision, laymen may carry out the following maintenance work on the product:

- > Remove dirt and grime with a soft cloth or cotton bud.
- General cleaning work
- Checking the welding contacts for cleanliness and sufficient contact force

19.3. Maintenance by specialists

The manufacturer and service stations approved by the manufacturer are able to carry out all necessary maintenance and repair work that will bring your product to a technically sound and safe condition. The following activities may only be carried out by the manufacturer or an authorized service station:

Replacement of components that require disassembly of the product.

19.4. Maintenance cycles for safe operation

Please note that the product is a technically demanding machine for field application. In accordance with the product-specific applicable standards and regulations in your country (eg DGUV V3), this must be regularly checked and maintained. The maintenance interval is 12 months, with heavy use shorter intervals are recommended.



Damage due to poor maintenance

If maintenance and service is omitted and maintenance intervals are exceeded, damage to the product or other property damage may result from product use.

Regular cleaning, checks and maintenance of the maintenance cycle can avoid this.

19.5. Measures after maintenance or servicing

After maintenance or servicing, be sure to inspect all safety features of the product and to ensure that the product functions properly and safely. Do not work with the product without prior checking.

19.6. Cleaning

To achieve an optimum work results the electrofusion control unit has to be handled with care and maintained frequently. Pollution by sand and dirt has to be avoided or, if necessary, removed with a soft cloth or a Q-tip.

19.7. Replacement of the welding terminals



Attention

Switch off the electrofusion control unit and disconnect it from the mains supply or generator!

The welding terminals should be checked on a regular basis and, if necessary, replaced as soon as they are damaged or lose contact force.

Exchange for straight welding terminals

- 1. Pull off the red resp. black PVC cap.
- Hold the front part of the brass contact with a pipe wrench and screw the welding terminal out of the brass socket by using a 7 mm wrench.
- If your electrofusion control unit is SmartFuse-capable, then note that, when changing the welding terminals, the red terminal contains a probe tip! Only use spare parts and welding terminals provided by PFS.
- 4. Screw a new terminal plug into the brass piece. Check for firm fit.
- Shove the PVC cap back over the welding terminal. Approximately 15 mm of the terminal must stand out of the PVC cap.

Exchange for angled welding terminals

- 1. Hold welding terminal and unscrew it using a 7 mm open-end wrench.
- If your electrofusion control unit is SmartFuse-capable, then note that, when changing the welding terminals, the red terminal contains a probe tip! Only use spare parts and welding terminals provided by PFS.
- 3. Screw in a new terminal plug, Make sure that the SmartFuse measuring tip is exactly centered.
- 4. Hand-tighten the welding terminal with the 7 mm open-end wrench.

20. Error messages E1-E30

Error messages are indicated by a bleep. A permanent bleep can be interrupted by pressing the red stop button.

Code	Error	Cause	Reaction	
-	Emergency cut-out	Welding was interrupted by pressing the red stop button	Welding is faulty! Start the welding process again with a different fitting.	
-	Memory overflow	Report memory is full	Print reports or deactivate the memory control option.	
-	System error	Selftest has detected an error in the system.	Immediately disconnect the device from the power supply. Do not connect the device to the power supply. Send it to a service point.	
-	Clock error	Internal clock does not work properly	Set clock, change battery if necessary	
-	Service	The recommended service interval of 12 months or 200 working hours are exceeded.	The device must be serviced by certified personnel or a service point. The device remains usable. The manufacturer is not liable until the device has undergone maintenance.	
E1	Contact error	Invalid SmartFuse resistance value	Clean terminals, use another fitting if possible	
E2	Power failure	Last welding was interrupted by a break of the power supply.	Welding is faulty! Prepare pipes again and use new fitting! Consult the dealer or manufacturer.	
		No sufficient electrical contact with the fitting	Check connection (welding terminals and welding contacts) to fitting.	
E3	No contact	Heating coil or welding cable is defect	Use another fitting Replace welding cable Consult the dealer or manufacturer.	
E4	Clean SmartFuse tip	Measuring tip of SmartFuse welding terminal is dirty	Check / clean welding terminal	
E5	Code error	Faulty input	Move the reading pen over the barcode in a continuous move with constant speed.	
	Code error	Barcode defect or error in code structure	Verification by manual input of the barcode digits	
E6	Temperature error	Ambient temperature is out of limit (- 10 to +50 °C)	Set up tent or take other measures to protect from heat. If the outside temperature is too cold, use heating.	
E7	Temp. meas. error	Temperature measurement is faulty Welding cable or temperature sensor damaged/defective	Plug in the removable welding cable again. Switch the device off and on again. Welding cable or sensor defect	
E8	Resistance error	Fitting resistance is out of the range of operation Fitting resistance is out of the valid working	Use a electrofusion control unit suitable for the fitting. Potentially faulty fitting. Use a new fitting.	
		range when using barcode input	Consult the dealer or manufacturer.	
E9	Device too hot	Temperature of transformer is too high	Let the device cool down for about 45 min	
E10	Frequency error	Input frequency out of working range (40-70 Hz)	Check generator.	
E11	Interturn short circuit	Current increases during welding by more than 15 % Short circuit in the heating coil	Welding is faulty! Consult the dealer or manufacturer.	
E12	Input volt. low	Input voltage < 190 V	Fully unwind mains supply cord, use mains supply cord with suitable cross section, readjust generator voltage	
E13	Input volt. high	Input voltage > 300 V	Adjust generator voltage to 260 V	
E14	Peak Error	Peak value of the input voltage too high	Check generator	
E15	Output volt. error	The output voltage deviates from the rated value. Generator RPM fluctuating or power too weak.	Check generator!	
E16	Current error (DUALMATIC)	Input voltage too high, resistance of the load too low	Check generator, use new fitting	

Code	Error	Cause	Reaction	
E17	Current low	Momentary interruption of welding current	Welding is faulty!	
E17		Current drops about 15-20 % within 3 s	Consult the dealer or manufacturer.	
E18	Current high	Output current is more than 15% higher than the starting current.	Short-circuit in the heating coil or welding cable If possible, test with another welding cable Consult the dealer or manufacturer.	
E19	Stop button	The red stop button was pressed during the welding process.	Welding is faulty! Start the welding process again with a different fitting.	
E20	Short circuit	Fault in electronics	Contact service	
E21	Power error	Output power too high	Start the welding process again with a different fitting.	
E22	CONTACT ERROR	Problem with the welding terminal	Contact service	
E23	Input current too high	Input voltage is too low, causing the current to rise.	Check voltage source Use an extension cable with a larger cross- section	
E24	BAD CONTACTS	Problem with the welding terminal	Contact service!	
E25	Out of range	Power demand of coupler is too high for the controller.	Use a more powerful controller to weld this coupler.	
E26	EMI Error1	Electronic out of order or defect	Contact service!	
E27	EMI Error2	Electronic out of order or defect	Contact service!	
E28	Current too high stage 1	(MAMMUT) Current too high	Contact service!	
E29	Current too high stage 2	(MAMMUT) Current too high	Contact service!	
E30	Voltage error in output stages	(MAMMUT) Load too high	Check voltage source Increase input voltage Contact service!	

20.1. Error messages E250-E285

These are advisory messages that appear after the electrofusion control unit is switched on. These indicate that a change was made to the system settings before the last switch-off. The error code appears as well as information about which system settings have been changed.

20.2. Bluetooth error messages

Errorcode	Cause	Reaction	
Checking BT module	Connector loose, defect in Bluetooth module	Restart the device and repeat action.	
		Electrofusion control unit must be checked.	
BT module not found	Connector loose, defect in Bluetooth module, Bluetooth module not available	Restart the device and repeat action. Electrofusion control unit must be checked.	

21. Maintenance and service by the customer service

The maintenance and the related checks are important for your safety and the continuous working reliability and safety of the product. Should the product, its components or accessories fail despite the great care taken in manufacturing and testing it, the necessary repairs should only be carried out by an after-sales service centre authorised by the manufacturer.

Have this product serviced only by a qualified person authorized by the manufacturer and only with original spare parts. This ensures that the safety of the product is maintained.

During maintenance, the product will be upgraded to the current technical standard of our devices and you get a 3-month guarantee on function for the maintained tool, excluding wearing parts.

21.1. Wearing parts

The following components of the product are wearing parts. These components may wear out through use. These parts are not covered by the 24-month warranty or the 3-month functional warranty after maintenance by the manufacturer or a service station authorized by the manufacturer.

Welding contacts

21.2. Addresses of service stations

Always contact your dealer or the manufacturer of the product.

21.3. Repackaging before transport

If the product is to be transported after use, it must be packed again in the packaging (boxes, suitcases) provided. This ensures that the product is best protected against transport damage.

22. Decommissioning, Disassemble, Disposal

The products, its components and accessories must be disposed of in an environment-friendly way sorted by materials. For products with hydraulic drive: Make sure that hydraulic oil and other lubricants are disposed of properly.

22.1. Environment-friendly disposal

22.1.1. General



EU countries only

According to the European Directive 2012/19/EU, power tools that are no longer usable must be collected and reused in an environmentally friendly manner. According to the European Directive 2006/66/EC, the same applies to defective or used rechargeable batteries/batteries.



All electrical devices of PF Schweißtechnologie GmbH, are marked with the symbol of a crossed-out garbage can. This symbol indicates that this device must not be disposed of with household waste.

PF Schweißtechnologie GmbH is registered with the German registration body EAR under the WEEE registration number 27521436. You are welcome to return your old device to us and we will take care of the disposal. Alternatively, upon request, we will be happy to provide you with the name of the nearest sales partner who can dispose of your old device for you.

 PF-Schweißtechnologie GmbH
 Tel.: +49-6631-9652-0

 Karl-Bröger-Str.10
 Fax.: +49-6631-9652-52

 DE-36304 Alsfeld
 E-Mail: info@pfs-gmbh.com

 Germany
 Web: www.pfs-gmbh.com

22.1.2. Batteries and accumulators

According to the Battery Ordinance, you as the end user are legally obligated to return all used rechargeable batteries and batteries. Disposal via household waste is prohibited!



The adjacent symbol indicates rechargeable batteries and batteries whose disposal in the household waste is prohibited. The following designations stand for the decisive heavy metal. These are affixed to the batteries and accumulators in question.

Always return your used rechargeable batteries and batteries to an authorized collection point. In this way, you fulfill the legal obligations and protect the environment.



Batteries and accumulators with lithium

To dispose of batteries and rechargeable batteries with lithium content, always contact a local specialist company. If disposed of or handled incorrectly, these batteries and accumulators can cause serious injury and fire. Never ship batteries and rechargeable batteries with lithium content without prior consultation with the carrier as well as the recipient.

23. Declaration of conformity CE

We declare herewith under our sole responsibility, that the product described under "Technical data" is compliant to the following standards or normative documents:

Document	Description	Edition	Classification
2006/95/EEC	Low-voltage directive	2007	D

This declaration loses its validity as soon as changes are made to the product without consulting the manufacturer first.

Technical documentation is

available at:

Achim Spychalski-Merle, CEO

PF-Schweißtechnologie GmbH Karl-Bröger-Str.10

36304 Alsfeld Germany

Place, date Alsfeld, 10.05.2019

The declaration printed here represents only an extract. The full document can be provided to you on request.

24. Administrator code

For electrofusion control units of the SmartFuse type, the administrator code is the inventory number of the electrofusion control unit set in the system settings read backwards.

Example:

Set inventory number: 12345678

Administrator code: 87654321

25. PLASSON subsidiaries worldwide

COUNTRY	NAME	INTERNET	PHONE	E-MAIL
Germany	PLASSON GmbH	www.plasson.de	+49 281 952 72-0	info@plasson.de
Italy	PLASSON Italia S.r.I Unipersonale	www.plasson.it	+39 143 609 9610	info@plasson.it
France	PLASSON France	www.plasson.fr	+33 160 664 66	commercial@plassonfrance.fr
United Kingdom	PLASSON UK Ltd	www.plasson.co.uk	+44 144 424 4446	sales@plasson.co.uk
Spain	PLASSON Spain, S.L.U.	www.plasson.es	+34 93 680 2778	plasson@plasson.es
Poland	PLASSON Polska Sp.z o.o.	www.plasson.pl	+48 22 727 90 64	biuro@plasson.pl
Romania	Baenninger Systeme România	www.plasson.ro	+40262220329	contact@bsr.ro
USA	PLASSON USA	www.plassonusa.com	+1 800-241-4175	info@plasson.com
Brazil	PLASSON do Brasil Ltda.	www.plasson-pead.com.br	+55 48 34319500 +55 48 991182325	plasson@plasson.com.br
South Africa	PLASSON South Africa	www.plasson.co.za	+27 11 708 3094	sales@plasson.co.za
Australia	PLASSON Australia	www.plasson.com.au	+61 1300 752 776	sales@plasson.com.au

General



Read complete manual! Observe fitting manifacturer's installation guide! Follow natinal and international directives!

Cleaning



Wipe around the pipe! Use approved cleaning agent! Use lint-free clothes!

Marking



Do not touch the cleaned welding areas! Mark insertion depth of fitting! Use approved markers!

Peeling



Remove dirt from the pipe! Mark welding area! Use rotational peeler tools only!

Alignment



Use proper alignment tools! Avoid mechanical stress on pipes and fitting! Wait for cooling before pressurising!



Plasson LTD. Maagan Michael, D.N. Menashe, 3780500, Israel Tel: +972-4-6394711 | Fax: +972-4-6394766 www.plasson.com | info@plasson.com